

Volkswagen Passat

VIN:
1VWBN7A35CCXXXXXX

2014



Theft

⚠ Needs attention



Purpose

⚠ Needs attention



Odometer

⚠ Needs attention



Legal status

✓ Looks good



Damage

⚠ Needs attention



+31

Data sources



We checked 900+ data sources in **35 countries**

Photos

2017-04

8 photos





Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

Beware

Vehicle was used as a rental!

Here's what we checked:



Rental

 **Record found**

Rental vehicle



Taxi

✓ No record found

No evidence of being used as a taxi



Transport

✓ No record found

No evidence of being used as a transport vehicle



Police

✓ No record found

No evidence of being used by police



Handicap

✓ No record found

No evidence of being used as a handicap vehicle



Driving school vehicle

✓ No record found

No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



Beware

Vehicle may be stolen!

Here's what we checked:



Currently wanted as stolen

⚠ Record found

Unknown date Lithuania



Stolen in the past

✓ No record found

Current status unknown



Stolen in the past

✓ No record found

Vehicle has been recovered

Police database stolen vehicle check completed in:



Lithuania

⚠ Record found



United States



Canada



United Kingdom



Czechia



Denmark



Finland



Hungary



Italy



Mexico



Poland



Netherlands



Romania



Slovakia



Slovenia

Odometer

Are there signs of mileage rollbacks or discrepancies?

Beware

This vehicle may have a fake mileage!

Note

- Last known mileage: 145,000 km
- Average mileage for similar models: 104,200 km
- 5 mileage records found

Rollback



Odometer records

2014-01 **102,000 km**

2015-01 **129,000 km**

2016-02 **155,000 km**

2017-12 **136,000 km**


 **Odometer Rollback**

2018-09 **145,000 km**

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

Note

Tech inspection passed 2017-02 in  **Lithuania**

Legal



Technical inspection (also known as MOT)

Passed 2017-02

 **Lithuania**

Has successfully passed
technical inspection



Scrap

✓ No record found

No record that vehicle was
marked as scrapped

Damage

Has this vehicle been damaged in the past? What was the value of the damages?


Beware

- This vehicle was damaged 3 times!
- This vehicle was severely damaged!

Note

Severe damages can leave structural issues, making the vehicle unsafe to drive!

Damage records



2018-03

 France


Severe damage

Estimated Repair Cost

€15,001 - €20,000

Possible Damage Cause

Unknown



2014-02

 Germany


Severe damage

Estimated Repair Cost

€5,001 - €10,000

Possible Damage Cause

Unknown



2014-02

 Lithuania

Damage

Estimated Repair Cost

€501 - €1,500

Possible Damage Cause

Unknown

Specs & equipment

What specs and equipment are on record for this vehicle?

Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Volkswagen



Model
Passat



Body type
Sedan



Manufacture year
2014



Powertrain displacement
2 L



Powertrain power
103 kW (138 hp)



Transmission type
Automatic



Plant location
Germany

Equipment

As received from the manufacturer

E0A

Special editions

No special edition

1PA

Lockable wheel bolts

Standard wheel bolts

0DI

Vehicle class differentiation units/platform components

Vehicle class differentiation -360-

7MG

Emissions standard

Emission standard EU5

1D0

Trailer hitch

Without trailer hitch

4UE

Airbag

Air bag for driver and front seat passenger

1E1

Activated carbon canister

Activated carbon canister

8ZH

Antennas

Antenna for AM/FM reception, "diversity"

6XU

Exterior mirrors

automatically dimming, electrically adjustable, separately heated

EA0

Follow-on warranty

Without subsequent warranty

5SL

Left exterior mirror

aspherical

5RQ

Right exterior mirror

convex

1X0

Drive layout

Front wheel drive

9WL

“Multimedia”, video/DVD/notebook connection

Multimedia socket for external audio source

A8B

Equipment levels

Basic equipment

1KW

Brake type in rear

Disc brakes, rear

J0L

Batteries

Battery 340 A (70 Ah)

1ZM

Brake type, front

Disc brakes, front (Geomet D)

4M3

Beverage holders

Cup holder

NY0

Battery/alternator capacity

Standard battery/alternator capacity

B0A

Component part sets with country-specific design requirements

Component parts set without country-specific design requirement

1S1

Tool kit and jack

Tool kit and jack

1AT

Brake systems

Electronic stabilization program (ESP)

0XR

Owner's manuals

Information kit in Lithuanian

9Z0

Operating voltage

Operating voltage 12V

9T0

Heated washer nozzles

Without heated washer nozzles

7QA

CD ROM/DVD/SD card

Without CD/DVD for navigation

7A0

CD changer/CD player

Without CD changer/CD player

2H0

Charism

Without "drive select"

QJ1

Chrome package

Chrome work package

C26

General operating permit, alterations

Operating permit, alteration

3S0

Roof rails/roof load rack

Without roof rails/roof load rack

3FA

Roof insert/convertible top

Without roof insert (standard roof)

1JA

Suspension system in rear

Rear shock absorption, basic design 1

G07

Suspension system in front

Front shock absorption

3X0

Ski bag

Without load-through provision

2G1

Insert for the filling up of unleaded fuel/fuel type

Insert for the filling up of unleaded fuel

OEM

Installation differentiation for vehicle components

Installation differentiation for transmission MQ 200 vehicle components

7AL

Theft protection system

Anti-theft alarm system, passenger compartment control, backup horn and towing protection

7TM

Inserts

Decorative inserts

7M0

Scuff plates

Plastic scuff plates in door apertures

7X0

Park distance control

Without park distance control

UF0

Electric interface for external use

Without electric interface

0FG

Manufacturing sequence differentiation

Mosel manufacturing sequence

6A0

Fire extinguishers

Without fire extinguisher

VF0

Pedal cluster

Standard pedal cluster

8K3

Headlight control

Separate daytime running lights with low beam assistant and “Coming Home” feature

UH2

Parking brake

Parking brake

7G0

Vehicle tracing system

Without preparation for VTS (vehicle tracking system)

F0A

Vehicle specifications

No special purpose vehicle, standard equipment

8GG

Alternators

Alternator 110 A

0G4

Transmission types/gearshift mechanisms

Cable gearshift

0YC

Weight category rear axle

Weight range 3 installation control only, no requirement forecast

L01

Weight category front axle

Suspension range 01 installation control only, no requirement forecast

TU0

Base engine

4-cylinder gasoline engine 1.4 L unit 03C.K

6M0

Tie down straps/net/pocket

Without tie down straps/net/pocket

8T0

Cruise control system

Without cruise control system (CCS)

VC0

Garage door opener

W/o remote-controlled garage door opener

G0K

Transmission specifications

6-speed manual transmission

6Y9

Cruise control system and speed limiter

W/o cruise control speed limit system

3P1

Brackets

Bracket for first aid kit and warning triangle

3NU

Rear seats

Rear seat bench unsplit, backrest split folding with center armrest

KH6

Heating and air conditioning system

Electronically controlled air conditioning system

8ID

Headlamps

Halogen twin headlights

FC0

Customized installation

Without customized installation

6T0

Interior light in footwell

Without interior light in footwell

U5A

Instrument clusters

Instrument insert, km/h speedometer

4L6

Breakaway interior rearview mirror

Breakaway interior rear view mirror, automatically dimming

K8B

Body style

Notchback

QK0

Camera/distance sensor

Without camera without distance sensor (driver assistance system)

6SE

Luggage compartment floor covering

Flat needle-punched trunk floor covering

4W0

Cassette and CD storage unit

Without cassette and CD storage unit

QA0

Child seats

Without child seat

0Y3

Climatic zones

Cold zones

QR0

Compass/road sign display

Without compass/traffic sign display/ traffic signs recognition

4D0

Seat ventilation/massage seat

Without seat ventilation/massage seat

3Q6

Rear head restraints

Three rear headrests

5ZJ

Head restraints

Front headrests

1Z0

Fuel quantity for initial filling

Initial standard fuel filling

1A2

Fuel systems

Fuel system for SI engine with direct injection (FSI)

5C0

Body measures

Without special body measures

6KJ

Radiator grille

Radiator grille with chrome-plated strip

6P1

Rear license plate carrier

License plate bracket rear (ECE)

6W1

Front license plate carrier

License plate bracket front (large)

5K7

Paint preservative/transit coating

Transport protection film (minimum protection) with additional transport protection measures

3GA

Rear luggage/load compartment floor

Without cargo area

FE0

Country codes

Without country code (no DVD player in vehicle)

L0L

Steering system arrangement

Left-hand drive vehicle

8S7

Reading light

Two reading lights front

1N3

Steering

Speed-related variable steering assist (Servotronic)

3H0

Backrest release

Without backrest release for front seats

8G0

Light control systems

Without light assistant

2P1

Loading edge protection

Plastic trunk sill protection

7P0

Lumbar support

Without lumbar support in seat backrests

1MR

Steering wheels

Leather steering wheel

AV1

Driving on the left/on the right

Driving on the right

8RM

Speaker installation

8 speakers (passive)

8Q1

Headlight range control

Headlight-range adjustment

6E3

Center armrest

Front center armrest

9Q5

Multi-function display/trip computer

Multi-function display with control

3I5

Center console

Center console

EM0

Driver alert system

Without Rest Assist

8Z5

Engine cooling system

Not hot country

D4X

Engine specifications

4-cyl. gasoline engine 1.4 l/90 kW TSI Base engine is TU0/TL1/TL8/T9B

4SG

Left vanity mirror

Left vanity mirror illuminated extractable sun visor

4TL

Right vanity mirror

Vanity mirror, right, illuminated extractable sun visor

7Q0

Navigation device

Without navigation device

8TC

Rear fog lamp

Rear fog light for driving on the right

8WA

Front fog lamp/additional headlamp

Without front fog light

1NH

Wheel covers

Full wheel covers

CZ0

Wheels

Steel wheels 6.5J x 16 with optimized weight

8AE

Radios

Radio "RCD310 MP3"

9JA

Smoker's/non-smoker's package

Non-smoking package

7K6

Direct tire pressure monitoring system

Flat tire indicator

NS0

Umbrella

Without umbrella(s)

H2F

Tires

Tires 205/55 R16 91H super-optimized rolling resistance

V0A

Tire suppliers

Tires w/o specification of tire brand

1G2

Spare wheel/breakdown kit

Steel spare wheel with original equipment tires

3QT

Restraint systems, front

3-point seat belts with tensioner and height adjustment, front

PA1

Leather steering wheel (3-spoke) with decorative aluminum inserts

True

WD4

Anti-theft alarm system "Plus"

True

WFA

Family package, Passat station wagon, Sweden

True

4X3

Side airbag

Side air bag front with curtain air bag

6Q2

Gearshift knob/handle

Leather gearshift knob/handle

2SB

Special labels/plates

Labels/plates in Polish, Estonian, Latvian, Lithuanian, Slovenian

8SG

Rear combination lamps

Standard taillight assemblies (type 2)

4E2

Lock operation for tailgate/trunk lid

Tailgate/trunk lid release from inside (electrically)

3TB

Front seat, left

Standard seat, front left

3SB

Front seat, right

Standard seat, front right

9P1

Seat belt check

Seat belt reminder, electric contact in buckle

3ZB

Outer rear seat belts

3-point seat belts, outer rear with ECE label

3C7

Center rear seat belts

3-point seat belt for center rear seat

N4C

Seat trim covers

Fabric seat covering

3L3

Seat adjustment

Manual height adjustment for front seats

4A0

Seat heater

Without seat heater

7L3

Start-stop system/regenerative braking

Without start/stop system without regenerative braking

8Y1

Horns

Two-tone horn

QH0

Audio-response system/voice control

Without voice control

7Y0

Lane change assist/lane keeping system

Without lane change assistant

4KC

Side and rear windows

Side and rear windows in heat-insulating glass

4B1

Protective side molding

Protective side molding

3Y0

Roll-up sun screen for rear and side windows

Without roll-up sun screen

7B6

Socket

12-volt socket(s)

2JB

Bumpers

Standard bumpers

QN0

Drawers under front seats

Without drawers under front seats

8X0

Headlamp washer system

Without headlight washer system

8N3

Windshield wiper intermittent control/ light/rain sensor

Windshield wiper intermittent control with rain sensor

3M0

Special registration measures

Without special measures

0NB

Nameplate set

Nameplate set in base trim

9A0

Special alarm systems

Without taxi alarm system

1Q0

Mass damper for steering wheels

Without mass damper for steering wheel

4K3

Door and lid locking system

Radio remote controlled central locking operated from inside and safe securing

B47

Type approval countries/countries with special requirements

Type approval the Baltic States

5D1

Carrier frequency for radio remote control

Carrier frequency 433.92 MHz-434.42 Mhz

3CA

Partition

Without partition

NT0

Transit coating

Transit coating (type 1)

3LC

Door and side trim panels

Door and side trim panel in foam film and woven fabric

QV0

TV reception/digital radio reception

W/o TV reception/digital radio reception

1VG

Installation parts for engine (engine mount system)

Installation parts for four-cylinder engine

1SA

Front underbody guard

Without additional front underbody guard

1EX

Identification plates

Special identification plate for EC for M1 passenger vehicle

2A0

Delivery equipment

Without delivery equipment

1T2

First aid kit / warning triangle

Warning triangle

9D0

Preparation for two-way radio installation

Without preparation for two-way radio installation

9F0

Preparation for sound combination for rotating beacon

Without sound combination for rotating emergency light and radio antenna preparation

9W0

Telephone / telematics

W/o car phone preparation/installation

9TC

Additional warning lights

Additional reflectors (door area)

QG1

Service interval prolongation

Service interval prolongation

7E0

Heat accumulator system/auxiliary heater

W/o heat accumulator/auxiliary heating

4GF

Windshield glass type

Windshield in heat-insulating glass

8FA

Second battery/battery installation

Without second battery

2WA

Additional tires (snow tires)

Without additional tires

0TA

Floor mats

Without floor mats

4ZE

Decorative trims

Black moldings

3B4

Additional child seat anchors

Child seat anchor for child seat system ISOFIX

9M0

Auxiliary heater

Without auxiliary/parking heater

UP0

Clocks

Analog clock

Timeline

5 records found

The timeline of records for this vehicle

Records

2014-01

 **Germany**



Was manufactured

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

2014-02

 **Poland**



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2017-02

 **Lithuania**



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

2017-11

 **Lithuania**



Damage detected

We have indications that this vehicle was recognised as damaged in this particular country (or state). Please refer to the “Damage” section for details.

2020-02

 **Lithuania**



Wanted

The vehicle was declared as stolen in this particular country (or state). It is purely the “origin of theft”, and does not cover all the jurisdictions otherwise involved.



+31

Data sources

We checked 900+ data sources in **35 countries**